

UNITED STATES DISTRICT COURT
DISTRICT OF MARYLAND

UNITED STATES OF AMERICA v. EFPLOIA SHIPPING CO., S.A.

Criminal No. MJG-11-0652

UNITED STATES OF AMERICA v. AQUAROSA SHIPPING, A/S

Criminal No. MJG-11-0671

Attachment B
GOVERNMENT'S
MOTION FOR WHISTLEBLOWER AWARD

1. USCG photograph of M/V Aquarosa in Baltimore.
2. USCG photograph of M/V Aquarosa in Baltimore
3. Photograph of check valve external and internal blocking mechanism.
4. Whistleblower photograph taken at sea of bypass connected to overboard piping.
5. Whistleblower photograph taken at sea of bypass connected from sludge pump.
6. USCG photograph of bypass flanges and hose discovered during inspection in Baltimore.
7. USCG photograph of bypass flange discovered during inspection in Baltimore.
- 8-11. Whistleblower photographs taken at sea of bypass connected to overboard piping.
12. USCG photograph showing condition of M/V Aquarosa overboard piping in Baltimore without bypass.
13. USCG photographs (left/center) showing locked overboard valve in Baltimore; and Whistleblower photograph taken at sea of overboard valve.
14. Whistleblower photograph taken at sea of bypass connected to boiler blowdown overboard valve.
15. USCG photograph showing boiler blowdown overboard valve during inspection in Baltimore (left); and Whistleblower photograph of boiler blowdown overboard valve taken at sea (right).
16. Whistleblower photograph of portable air pump (Weldon pump) being used for internal transfers of waste oil.
17. Whistleblower photograph taken at sea of calendar and sounding log showing drop in tank volume.
18. Whistleblower photograph taken at sea showing accumulation of oily rags in plastic bags.
19. Whistleblower photograph taken at sea showing oily rags in plastic bags on ship's deck.



Exhibit 1



Exhibit 2



Exhibit 3



Exhibit 4



Exhibit 5



Exhibit 6



Exhibit 8



Exhibit 9



Exhibit 10



Exhibit 11



Exhibit 12






Exhibit 14




Exhibit 15





Exhibit 18



Exhibit 19